APPENDIX A SUPPORTING DATA

CABRILLO PORT, LNG TERMINAL PROJECT

PRELIMINARY GEOTECHNICAL STUDY,

SUMMARIZING SUBSURFACE CONDITIONS AT SOUTHLAND SOD FARMS

Document No.: WCLNG-BHP-DEO-GR-00-216-0

Revision No. A Issue Date: April 21, 2005 Project No. 3390.002



CONFIDENTIAL

APPENDIX A SUPPORTING DATA

Copies of the following geotechnical data developed for the BHP Port Cabrillo Project are included in the appendix to this report:

•	Log of Boring and Test Results, Boring DH-1	Plate A-1a and A-1b
•	Composite Vibracore Log	Plate A-2
•	Key to Terms and Symbols Used on Logs	Plate A-3
•	Descriptions of Drop Core and Grab Samples	Plate A-4
•	Grain Size Curves	Plate A-5

The log and data presented are a simplification of actual conditions encountered at the time of sampling at the sample location. Subsurface conditions may differ at other locations and with the passage of time.

LOG OF BORING AND TEST RESULTS

BHP Cabrillo Port HDD Shore Crossing Project Ventura County, California



The log and data presented are a simplification of actual conditions encountered at the time of sampling at the sample location. Subsurface conditions may differ at other locations and with the passage of time.

For symbol identification, refer to Key to Terms & Symbols Used on Logs.

LOG OF BORING AND TEST RESULTS BORING DH-1



						LOCATION:							Ωm
ELEVATION, m	DEPTH, m	MATERIAL SYMBOL	SAMPLE NO.	SAMPLERS	SAMPLER BLOW COUNT	N 3,777,574 E 299,127 SURFACE EL: -14.0 m +/- (rel. MLLW datum) MATERIAL DESCRIPTION	UNIT WET WEIGHT, kN/m³	UNIT DRY WEIGHT, KN/m³	WATER CONTENT, %	% PASSING #200 SIEVE	LIQUID LIMIT, %	PLASTICITY INDEX, %	UNDRAINED SHEAR STRENGTH, S _u , kPa
-				\bigvee		Silty Fine SAND (SM):							رەر
- - - 15	- - 1- -					- Sandy Silt and Silty Fine Sand below 1.5 meters			- · - · -				
-	-			\gg									
16	2-			\gg			L · – · -						
17	- - - 3-			\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\				_ · _ · -	- · — · —	· · — · —	. — . —		
18				\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\					- · - · -				
	- - - 5-			\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		Log is composite of four vibracores collected within a 45-meter-radius of latitude 34 7' 11", longitude 119 10' 41"							
19 - - -	5-									. — . —	. — . —		
20	6-						<u> </u>						

The log and data presented are a simplification of actual conditions encountered at the time of drilling at the drilled location. Subsurface conditions may differ at other locations and with the passage of time. COMPLETION DEPTH: 4.6 m

DRILLING DATE: September 10, 2003

COMPOSITE VIBRACORE LOG

BHP Cabrillo Port HDD Shore Crossing Project Oxnard, California





Ę	_		O.		Ž Ę	LOCATION: The drill hole location referencing local landmarks or coordinates		General Notes		
ELEVATION, m	DEРТН, m	MATERIAL SYMBOL	ž				Soil Texture Symbol			
EVAT	DEPT	AATE SYM	SURFACE EL: Using local, MSL, MLLW or other datum		m	Sloped line in symbol column indicates				
			Ś	0,	BLO	MATERIAL DESCRIPTION		transitional boundary		
				\bigvee		Well graded GRAVEL (GW)		Samplers and sampler dimensions (unless otherwise noted in report text) are as follows:		
12	2 -		1	M	25	, ,		Symbol for:		
						Poorly graded GRAVEL (GP)		1 SPT Sampler, driven 34.9 mm ID, 50.8 mm OD		
14	4 -		2		(25)		ç	2 CA Liner Sampler, driven 60.3 mm ID. 76.2 mm OD		
						Well graded SAND (SW)	ARSE	3 CA Liner Sampler, disturbed		
16	6 -		3		(25)		S E	60.3 mm ID, 76.2 mm OD 4 Thin-walled Tube, pushed		
			3		(25)	Poorly graded SAND (SP)	G	73.0 mm ID, 76.2 mm OD 5 Bulk Bag Sample (from cuttings)		
-18	8 -			1111			Ř	6 CA Liner Sampler, Bagged		
			4		(25)	Silty SAND (SM)	ΪN	7 Hand Auger Sample		
20	10-			1;1;1			Ë	8 CME Core Sample 9 Pitcher Sample		
			5	\bigotimes	457/ 726	Clayey SAND (SC)		10 Lexan Sample		
22	12 -		Ū	\boxtimes	mm			11 Vibracore Sample		
				\times		Silty, Clayey SAND (SC-SM)		12 No Sample Recovered 13 Sonic Soil Core Sample		
24	14 -		6	\bowtie						
		Ш		V		Elastic SILT (MH)	_	Sampler Driving Resistance Number of blows with 140 lb. hammer, falling		
26	16 -	*****	7				F	30" to drive sampler 1 ft. after seating sampler 6"; for example,		
				И		SILT (ML)	N E	Blows/ft Description		
28	18 -		0		508/	City OLAY (CLAM)	G	25 25 blows drove sampler 305 mm after initial 152 mm of seating		
30	20-		8		610 mm	Silty CLAY (CL-ML)	Ŕ	86/280 After driving sampler the initial 152 mm of seating, 36 blows drove		
-30	20			72		Fat CLAY (CH)	N	sampler through the second 152 mm interval, and 50 blows drove		
-32	22 -		9		(25)	Tat GEAT (GIT)	Ë	the sampler 128 mm into the third interval		
52				<u> </u>		Lean CLAY (CL)		50/152 50 blows drove sampler 152 mm after initial 152 mm of seating		
34	24 -		10	الالله	762/ 762			Ref/76 50 blows drove sampler 76 mm		
				HIIIII	mm	CONGLOMERATE		during initial 152 mm seating interval		
36	26 -			\boxtimes	508/			Blow counts for California Liner Sampler shown in ()		
			11	\gg	610 mm	SANDSTONE		Length of sample symbol approximates		
38	28 -			$\stackrel{\sim}{-}$				recovery length Classification of Soils per ASTM D2487		
			12	•		SILTSTONE		or D2488		
40	30-						Ŗ	Geologic Formation noted in bold font at the top of interpreted interval		
			13			MUDSTONE	ROCK	Strength Legend		
-42	32 -	/////	10				K	Q = Unconfined Compression u = Unconsolidated Undrained Triaxial		
						CLAYSTONE		t = Torvane		
-44	34 -	KA						p = Pocket Penetrometer m = Miniature Vane		
						BASALT		Water Level Symbols		
46	36 -							☐ Initial or perched water level☐ ☐ Final ground water level☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐		
						ANDESITE BRECCIA		Seepages encountered		
48	38 -	0-0				Parisas auditas Para M. C. C.		Rock Quality Designation (RQD) is the sum of recovered core pieces greater than 102 mm divided by the length of		
						Paving and/or Base Materials		than 102 mm divided by the length of the cored interval.		


KEY TO TERMS & SYMBOLS USED ON LOGS



Drop Core and Grab Sample Location	Water Depth MLLW Meters (feet)	Sample Depth Meters (feet)	Sample Description
C-03A	16.5 (54.1)	0 to 0.15 (0 to 0.5)	Silty Fine SAND (SM), gray, with shell fragments, organics, and plant material
C-04B	21.0 (68.9)	0 to 0.15 (0 to 0.5)	Silty Fine SAND (SM), gray, with shell fragments and plant material
C-06C	32.0 (105)	0 to 0.15 (0 to 0.5)	Sandy SILT (ML), gray, with shell fragments and plant material
C-08A	40.0	0 to 0.38 (0 to 1.25)	Sandy SILT (ML), dark gray, with shell fragments, plant material, sand pockets, and sand partings
C-00A	(131.2)	0.38 to 0.46 (1.25 to 1.5)	Lean CLAY (CL), very soft, very dark gray
C-10A	46.0 (151)	0 to 0.15 (0 to 0.5)	Silty SAND (SM), gray, with shell fragments and plant material

DESCRIPTIONS OF DROP CORE AND GRAB SAMPLES RECOVERED ALONG PROPOSED HDD ALIGNMENT





	LEGEN	D	CLASSIFICATION	<u>Cc</u>	<u>Cu</u>	
	(location)	(depth,m)				
0	DH-1	3.7	SAND with silt (SP-SM)	1.0	2.8	
•	DH-1	9.4	Silty SAND (SM)	1.0	1.8	
Δ	DH-1	10.7	Silty SAND (SM)			
A	DH-1	12.5	Silty SAND (SM)	0.9	1.6	
\odot	DH-1	27.4	Sandy SILT (ML)			
۰	DH-1	47.2	Fine Sandy SILT (ML)			
	DH-1	52.0	Fine Sandy SILT (ML)			
	C-3a	0.0	Silty SAND (SM)	1.6	2.3	
•	C-4b	0.0	Silty SAND (SM)	4.9	7.2	
\oplus	C-6c	0.0	Sandy SILT (ML)	3.0	5.8	
	C-8a	0.1	Sandy SILT (ML)	2.5	5.0	
•	C-10a	0.0	Silty SAND (SM)	1.7	2.3	

GRAIN SIZE CURVES

BHP Cabrillo Port HDD Shore Crossing Desktop Study Ventura County, California

